

## Match the foil



Correctly matched foil dimensions are a must. The machine has a knife to cut off the excess foil, but it is more convenient economical to match the foil to the product. When choosing the foil, two parameters should be considered: product length and height.

Match the foil according to the formula:

**L** + ( **2 x H** ) = Foil dimension in mm \* ( 2 x H ) depending what overlap you wish to obtain

L -product length W - product width H -product height

## Wrapping



## Weld types



\* standard weld as shown in Figure D