

Pneumatic Tacker 380/16-400 OC

The light but powerful tacker of the BeA 400 series uses staples type 80/380 in leg lengths from 5/16" to 5/8". The 380/16-400 OC stapler flares the staple legs outward as they penetrate the material being fastened. The outward clinch nose can be adjusted to control the amount of leg flare. The low air consumption, long service life and ease of maintenance make this tool a cost saver. The bottomloading magazine allows for quick and easy loading.



Popular applications:

Fastening ticking fabric to foam rubber box spring borders. Textile-stapling layers of fabric togehter in pattern cutting.

Technical Data

Model:	380/16-400 OC	
	Outward clinch	
Part number:	120000024	
Loading type:	bottom loading	
Staple type:	80, 380	
Magazine capacity:	157	
Standard load, strips x staples/strip:	1 x 125 Type 80 / 1 x 150 Type 380	
Operating pressure:	75-90 P.S.I.	
Maximum air pressure:	90 P.S.I.	
Air consumption:	.01 cu. ft./cycle @ 90 P.S.I.	
Recommended hose I.D.:	ø 3/8"	
Weight:	2.26 lbs.	
Itoma gunnical with tool	On anoting instructions, anone norts list & somios instructions	

Items supplied with tool:

Operating instructions, spare parts list & service instructions.

Subject to technical modifications.

Accessories:	
Part number	Description
14403330	Remote firing valve
14403535	Stationary mounting fixture

All BeA pneumatic tools can be jig mounted. We supply the necessary accessories. This tool conforms to the EC Directive for Machinery (89/392 EWG)

Product Sheet 400 OC



Pneumatic Tacker 380/16-400 OC



BeA Fasteners U.S.A. beA Fasteners 0.5.A. 2100-120 Fairfax Road Greensboro, NC 27407 Phone: (336) 510-4232 Fax: (336) 510-4233

Staple types 80/380



Description	L = Length
-	inches
80/04 NK	5/32"
80/05 NK	3/16"
380/06 NK	1/4"
380/08 NK	5/16"
380/10 NK	3/8"
380/12 NK	1/2"
380/14 NK	9/16"
380/16 NKS	5/8"

Other lengths and finishes are also available on request.

Fastener nomenclature:

- NK = Galvanized steel NKS = Galvanized steel, high carbon
- BK = Brite steel BKS = Brite steel, high carbon

HZ = Resin coatedNR DP = Stainless steel = Divergent point